HOW TO APPLY YOUR ADHESIVES



1. Clean and remove all grease from the surface on which you want to stick. Make the surface dry.



2. Put the sticker with the slicon base papern on the surface and tape it in order to keep its position.



3. Tear adhesive sticker and silicon base paper apart. Cut the half of the silicon base paper away.



4. Reposition the sticker and use a plastic part to "iron" the sticker on the surface

5. Slowly remove the silicon base paper while rubbing with the sticker with a plastic part



6 . Slowly remove surface paper in a 180° angle.

REMARK: Maximum sticker adhesion 48 hours after application.